

**February 23 & 24, 2025 — Photo Documentation Exterior: '02\_2025\_Exterior11x17\_HouseWalls"**

**To examine cedar shingle siding conditions & problem areas,  
roofline drip issues, insurance repair status wall Back Ram South**





South Face-Hancock Hall 2



South Face-Hancock Hall 3



Dining Room  
South Face-Hancock Hall 4



Dining Room  
South Face-Hancock Hall 5



South Face-Hancock Hall 6



last window  
South Face-Hancock Hall 7



East Face-Wells Common 8



East Face-Wells Common 9



North Face-Arena/Field 10



North Face-Arena/Field 11



East-North Corner1-Arena/Field 12



East-North Corner2-Arena/Field 13



South Face–Hancock Hall 14



West - Riverside 15



East/North Corner-Wells Common 16